Status: Draft	Approval Date:	Approved By:				
Part I: Summary						
PHA Name: Pinal County Housing Author	rity Loc	cality (City/County & State				
PHA Number: AZ010	X Orig	ginal 5-Year Plan	Revised	5-Year Plan (Revision No	:	
Development Number and Name	Work Sta	atement for Year	Work Statement for	Work Statement for	Work Statement for	Work Statement for
Development Number and Name	1 2024		Year 2 2025	Year 3 2026	Year 4 2027	Year 4 2028
PINAL (AZ010000001)	\$419,060.	0.00	\$502,872.00	\$502,872.00	\$502,872.00	\$502,872.00

Work Statement for Year 1 2024				
Development Number/Name	General Description of Major Work Categories	Estimated Cost		
PINAL (AZ010000001)		\$419,060.00		
Administration(Administration (1410)-Salaries)	Salary compensation for Capital Fund Manager	\$37,000.00		
Operations(Operations (1406))	Operations budget for general operations need as they arises.	\$80,149.00		
Landscaping/Erosion Control Eloy Development (Non-Dwelling Site Work (1480) - Asphalt-Concrete-Paving, Non-Dewling Site Work (1480) - Landscape, Non-Dweling Site Work (1480) - Storm Drainage)	Install granite rocks, shrubbery, and pavers. Provide 3" curb cuts and adjust grade around buildings adding clean fill where needed	\$191,775.00		
City Sewer Connections (Dwelling Unit-Site Work (1480)-Sewer Lines - Mains)	Abondon old septic system and connect to Apache Junction	\$110,136.00		
Subtotal of Estimated Cost		\$419,060.00		

Work Statement for Year 2 2025				
Development Number/Name	General Description of Major Work Categories	Estimated Cost		
PINAL (AZ010000001)		\$502,872.00		
Administration(Administration (1410)-Salaries)	Salary compensation for Capital Fund Manager	\$37,000.00		
Operations(Operations (1406))	Operations budget for general operations need as they arises.	\$80,149.00		
Paint unit exterior at 10-0 Scattered sites- Coolidge (Dweling Unit Exterior (1480) - Exterior Paint and Caulking)	Stucco repair, replacing facia, and paint the exterior of scattered sites located in Coolidge (8 units total)	\$26,000.00		
Paint unit exterior at 10-3 Scattered sites- Eloy (Dweling Unit Exterior (1480) - Exterior Paint and Caulking)	Stucco repair, replacing facia, and paint the exterior of 15 buildings located in Eloy	\$50,000.00		
HVAC Replacement (Dwelling Unit Exterior (1480) - Other	Replace HVAC units as the become inoperable. Location to be determined based on need.			
Modernize kitchens and bathrooms in 3 units(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non-cyclical), Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non-routine), Dwelling Unit-Interior (1480)-Interior Painting (non-routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)Tubs and Showers)	Kitchens to include replacement of cabinets, sink, range hood, light fixture and counter tops. Bathrooms to include replacement of bathtub, sink, exhaust fan, light fixture and medicine cabinet. Remove fiberglass tub surround and replace with tile. Replace VCT flooring throughout the unit.	\$184,124.00		
City Sewer Connections (Dwelling Unit-Site Work (1480)-Sewer Lines - Mains)	Abondon old septic system and connect to Apache Junction	\$85,599.00		
Subtotal of Estimated Cost		\$502,872.00		

Work Statement for Year 3 2026				
Development Number/Name	General Description of Major Work Categories	Estimated Cost		
PINAL (AZ010000001)		\$502,872.00		
Administration(Administration (1410)-Salaries)	Salary compensation for Capital Fund Manager	\$37,000.00		
Operations(Operations (1406))	Operations budget for general operations need as they arises.	\$80,149.00		
Landscaping/Erosion Control 10-2 Maricopa Development (Non-Dwelling Site Work (1480)- Asphalt-Concrete-Paving, Non-Dewling Site Work (1480) - Storm		\$110,000.00		
Paint unit exterior at 10-5 and 10-10 Scattered sites- Casa Grande (Dweling Unit Exterior (1480) - Exterior Paint and Caulking)	Stucco repair, replacing facia, and paint the exterior of scattered sites located in Casa Grande (27 units total)	\$78,000.00		
Paint unit exterior on Quail in Apache Junction (Dweling Unit Exterior (1480) - Exterior Paint and Caulking)	Stucco repair, replacing facia, and paint the exterior of 2 duplex buildings on Quail in Apache Junction	\$7,400.00		
HVAC Replacement (Dwelling Unit Exterior (1480) - Other	Replace HVAC units as the become inoperable. Location to be determined based on need.	\$40,000.00		
Modernize kitchens and bathrooms in 2 units (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non-cyclical), Dwelling Unit-Interior	Kitchens to include replacement of cabinets, sink, range hood, light fixture and counter tops. Bathrooms to include replacement of bathtub, sink, exhaust fan,	\$150,323.00		
Subtotal of Estimated Cost	3 4 1 1 1	\$502,872.00		

Work Statement for Year 4 2027			
Development Number/Name	General Description of Major Work Categories	Estimated Cost	
PINAL (AZ010000001)		\$502,872.00	
Administration(Administration (1410)-Salaries)	Salary compensation for Capital Fund Manager	\$37,000.00	
Operations(Operations (1406))	Operations budget for general operations need as they arises.	\$80,149.00	
HVAC Replacement (Dwelling Unit Exterior (1480) - Other	Replace HVAC units as the become inoperable. Location to be determined based on need.	\$40,000.00	
Modernize Bathroom and Window Installation (Dwelling Unit Exterior (1480) - Windows, Dwelling Unitneterior 1480) - Bathroom Counters and sinks, Dwelling Unit - Interior (1480) - Bathroom Flooring (non yelical), Dwelling Unit - Interior (1480) - Electrical, Dwelling Unit- Interior (1480) - Interior Painting non routine), Dwelling Unit- Interior (1480) - Plumbing, Dwelling Unit- Interior (1480) - Tubs and howers)	Unit 502 Navaho #1 Bathroom to include replacement of bathtub, sink, exhaust fan, light fixtures, and medicine cabinet. Remove fiberglass tub surrounding and tile and replace with shower pan insert. Replace VCT flooring.  Windows to include installation of dual pane windows throughout unit.	\$20,000.00	
Slurry Seal Eleven Mile Corner Road (Non Dwelling Site Work (1480) - Asphalt - Concrete - Paving	Eleven Mile Corner Road - Provide are protection. Remove loose debris from surface. Seal cracks. Apply slurry seal to existing asphalt. Clean up.	\$75,000.00	
Modernize kitchens and bathrooms in 2 units(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non-cyclical),Dwelling Unit-Interior (1480)Electrical, Dwelling Unit-Interior (1480)-Flooring (non-routine),Dwelling Unit-Interior (1480)-Interior Painting (non-routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)Tubs and Showers)	Kitchens to include replacement of cabinets, sink, range hood, light fixture and counter tops. Bathrooms to include replacement of bathtub, sink, exhaust fan, light fixture and medicine cabinet. Remove fiberglass tub surround and replace with tile. Replace VCT flooring throughout the unit.	\$171,323.00	
Landscaping/Erosion Control 10-0 Coolidge Scattered sites-Development (Non-Dwelling Site Work (1480)- Asphalt-Concrete-Paving, Non-Dewling Site Work (1480) - Landscape, Non-Dweling Site Work (1480) - Storm Drainage)	Install granite rocks, shrubbery, and pavers. Provide 3" curb cuts and adjust grade around buildings adding clean fill where needed	\$79,400.00	
Subtotal of Estimated Cost		\$502,872.00	

Work Statement for Year 5 2028				
Development Number/Name	General Description of Major Work Categories	Estimated Cost		
PINAL (AZ010000001)		\$502,872.00		
Administration(Administration (1410)-Salaries)	Salary compensation for Capital Fund Manager	\$37,000.00		
Operations(Operations (1406))	For general Operations budget to use as need arises.	\$80,149.00		
Landscaping/Erosion Control 10 - 5 and 10-0 Scattered sites- Casa Grande Development (Non-Dwelling Site Work (1480) - Asphalt-Concrete-Paving, Non-Dewling Site Work (1480) - Landscape, Non-Dweling Site Work (1480) - Storm Drainage)	Install granite rocks, shrubbery, and pavers. Provide 3" curb cuts and adjust grade around buildings adding clean fill where needed	\$130,000.00		
Landscaping/Erosion Control 10-8 and 10-10 Scattered sites- Apache Junction Development (Non-Dwelling Site Work (1480) - Asphalt-Concrete-Paving, Non-Dewling Site Work (1480) - Landscape, Non-Dweling Site Work (1480) - Storm Drainage)	Install granite rocks, shrubbery, and pavers. Provide 3" curb cuts and adjust grade around buildings adding clean fill where needed	\$130,000.00		
Paint unit exterior of 10-8 Apache Junction (Dweling Unit Exterior (1480) - Exterior Paint and Caulking)	Stucco repair, replacing facia, and paint the exterior of 25 units in Apache Junction Units on	\$70,000.00		
Modernize kitchens and bathrooms in 1 units(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non-cyclical), Dwelling Unit-Interior (1480)Electrical, Dwelling Unit-Interior (1480)-Flooring (non-routine), Dwelling Unit-Interior (1480)-Interior Painting (non-routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)Tubs and Showers)	Kitchens to include replacement of cabinets, sink, range hood, light fixture and counter tops. Bathrooms to include replacement of bathtub, sink, exhaust fan, light fixture and medicine cabinet. Remove fiberglass tub surround and replace with tile. Replace VCT flooring throughout the unit.	\$55,723.00		
Subtotal of Estimated Cost		\$502,872.00		