

Work Order Summary Report



Service Type:	INSTALL
Service Reason:	

Customer Name:	Pinal County, Arizona
Customer Number:	32018

City, State, Zip:	Florence, AZ 85132
Office Phone:	
Contact:	
Email:	

Equipment Type	Qty	Contract Type	Certification Release Name	Firmware	Backup Battery Date	Coin Battery Date
DS850	1	ANNUAL-MAINT, POST	EVS 6.3.0.0	4.2.0.0		6/26/2023
DS950 (i) Digital Central Scanner v1. Paper Tabulator	4	ANNUAL-MAINT		4.2.0.0		
ExpressVote V2	110	ANNUAL-MAINT	EVS 6.3.0.0	4.2.1.0	7/5/2019	5/3/2021

Serial Num	Work Order	Finish Date	Part #	Part Description	Qty	Comments	Executed By	Cust Signature
DS950 (32018)	129156	6/5/2024				Completed DS950 Installation. Passed all testing including Hash verification on units: DS9523090681, DS9523090682, DS9523090683, DS9523090684		
DS9523090681.0 1	129160	6/5/2024				Completed DS950 Installation. Passed all testing including Hash verification.		
DS9523090682.0 1	129157	6/5/2024				Completed DS950 Installation. Passed all testing including Hash verification.		
DS9523090683.0 1	129158	6/5/2024				Completed DS950 Installation. Passed all testing including Hash verification.		
DS9523090684.0 1	129159	6/5/2024				Completed DS950 Installation. Passed all testing including Hash verification.		